

**LEACHATE COLLECTION WELLS
OM&M MONITORING AND BAILING DATA SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

DATE: October 8, 2007


TECHNICIAN NAME: Patterson

TECHNICIAN SIGNATURE: 

WELL ID	BOTTOM OF WELL AFTER CONSTRUCT-ED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
			Start	Finish	Start			Finish			Start	Finish		
					1 st Rdg.	2nd Rdg.	3 rd Rdg.	1 st Rdg.	2nd Rdg.	3 rd Rdg.				
LC-1	22.25	22.24	0900	0915	19.71	19.71	19.71	21.69	21.69	21.69				
LC-2	21.90	21.90	0925	0937	12.88	12.88	12.88	21.21	21.21	21.21				
LC-3	22.20	22.19	0950	0953	21.80	21.80	21.80							less than 1 foot of product
LC-4	21.90	21.91	1002	1016	12.72	12.72	12.72	21.18	21.18	21.18				

W:\Interim\OpMain\Mon\LeachateCollectionWells\WorkPlan\FieldForms\February2007\Feb507LC-WellsM&B(YF1).doc

**LEACHATE COLLECTION WELLS
OM&M INSPECTION SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
Baltazar			October 8, 2007

ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (✓) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)	OK	OK	OK	OK		✓✓✓✓
Well Casing and Cap/Plug	OK	OK	OK	OK		✓✓✓✓
Liquid Present in Well Box	NO	NO	NO	NO		✓✓✓✓
Other:						
Other:						
Other:						

W:\In\air\OpMain\Mon\LeachateCollectionWells\WorkPlan\FieldForm\Feb507LC-Wells Inspection(YF) doc

DAILY FIELD REPORT

[illegible]

Note: Specific System Data and Observations are Included on "OM&M Inspection Sheets" and "OM&M Monitoring and Bailing Data Sheets"

DAILY FIELD REPORT
WASTE DISPOSAL, INC
SANTA FE SPRINGS, CALIFORNIA

TRC**FIGURE J.1**